



## DCP v.2.9.3 rc7 Changelog

### Modifications

- Default output level modified from 0dB to -6dB

### Bugs Fixes

- Fixed a bug that happened when two channels were paired and the equalizer was reset. Then it happened that if you changed a parameter of an equalizer control point, the value of the wrong band was changed.
- Fix for the creation of the on/off input/output clip mask command that caused an interruption of communication during the writing of parameters from files (default/last saved/PC). Note that this bug was present not only in rc6 but also in rc5.
- Fix of the auto-save preset function (for "last saved" use) after the logout from the DSP.
- Fix of mismatching activation in selection of channel 06 (minor interface view issue).

### New Functions

- Output Clipping indicators (as new column in the Main Window)
- Output Level Controls (new menu in the Main Window)
  - Default: set each output level at -6dB
  - Max: set each output level at 0db
  - Auto ON/OFF: while AUTO ON is selected, every time an output clip signal is detected, each output level is decreased by 0.1dB
- Input Clipping indicators (IO Window)